

Existing Conditions

Existing Bright to I-74 Route: State Line, North Dearborn, Whites Hill, SR 46

- Posted Speeds are 45 mph
- Two lanes, Minimal Shoulders
- Classified as Rural Collectors
- Do Not Meet Current INDOT* Design Criteria
- Roadside Obstructions or Hazards
- Pavement in Fair to Good Condition

North Dearborn Problems

- Three segments with sharp curves between State Line and Whites Hill Roads
 - East of King Drive
 - Curve at Bright Leaf Drive and Henderson Road.
 - Reverse curve between Carr Road and the driveway for the Dearborn Hills United Methodist Church
- Substandard vertical curves



Whites Hill Problems

- Three segments with sharp curves between North Dearborn and SR 46
 - Gaynor Ridge Road intersection limited site distance
 - South of Price Lane for approximately 1,500 feet
 - From Price Lane to north of I-74 has a 20 mph advisory speed due to horizontal curvature and grades
- Grades exceed standard 7% for one third of the length & max grades exceed 11%
- Substandard vertical curves



* Indiana Department of Transportation